
BCS Absolute Radiance Difference, (SRV0545-6)
I4 Warm-up, HAM A (quadratic poly_fit)
BCS ARD
1
0
-1
-2
-3
260
280
300
320
OBC Temperature (K)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


BCS Absolute Radiance Difference, (SRV0545-6)
I5 Warm-up, HAM A (quadratic poly_fit)
BCS ARD
0.4
0.3
0.2
0.1
0.0
-0.1
-0.2
260
280
300
320
OBC Temperature (K)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


BCS Absolute Radiance Difference, (SRV0545-6)
M12 Warm-up, HAM A (quadratic poly_fit)
BCS ARD
1.5
1.0
0.5
0.0
-0.5
-1.0
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M13 Warm-up, HAM A (quadratic poly_fit)
BCS ARD
1.0
0.5
0.0
-0.5
-1.0
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M14 Warm-up, HAM A (quadratic poly_fit)
BCS ARD
0.30
0.25
0.20
0.15
0.10
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M15 Warm-up, HAM A (quadratic poly_fit)
BCS ARD
0.25
0.20
0.15
0.10
0.05
0.00
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M16A Warm-up, HAM A (quadratic poly_fit)
0.20
0.15
0.10
0.05
0.00
-0.05
BCS ARD
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M16B Warm-up, HAM A (quadratic poly_fit)
BCS ARD
0.14
0.12
0.10
0.08
0.06
0.04
0.02
0.00
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M16 Warm-up, HAM A (quadratic poly_fit)
1.0
0.8
0.6
0.4
0.2
0.0
BCS ARD
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
I4 Cool-down, HAM A (quadratic poly_fit)
BCS ARD
0.60
0.55
0.50
0.45
0.40
0.35
0.30
0.25
260
280
300
320
OBC Temperature (K)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


BCS Absolute Radiance Difference, (SRV0545-6)
I5 Cool-down, HAM A (quadratic poly_fit)
0.10
0.05
0.00
-0.05
-0.10
BCS ARD
260
280
300
320
OBC Temperature (K)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


BCS Absolute Radiance Difference, (SRV0545-6)
M12 Cool-down, HAM A (quadratic poly_fit)
0.60
0.55
0.50
0.45
0.40
0.35
BCS ARD
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M13 Cool-down, HAM A (quadratic poly_fit)
BCS ARD
0.55
0.50
0.45
0.40
0.35
0.30
0.25
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M14 Cool-down, HAM A (quadratic poly_fit)
0.35
0.30
0.25
0.20
0.15
BCS ARD
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M15 Cool-down, HAM A (quadratic poly_fit)
BCS ARD
0.18
0.16
0.14
0.12
0.10
0.08
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M16A Cool-down, HAM A (quadratic poly_fit)
BCS ARD
0.12
0.10
0.08
0.06
0.04
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M16B Cool-down, HAM A (quadratic poly_fit)
BCS ARD
0.14
0.12
0.10
0.08
0.06
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


BCS Absolute Radiance Difference, (SRV0545-6)
M16 Cool-down, HAM A (quadratic poly_fit)
1.0
0.8
0.6
0.4
0.2
0.0
BCS ARD
260
280
300
320
OBC Temperature (K)
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16

Warm-up BCS Absolute Radiance Difference, (SRV0545-6)




Cool-down BCS Absolute Radiance Difference, (SRV0545-6)
0.6
0.4
0.2
0.0
BCS ARD
260
280
300
320
OBC Temperature (K)
I4
I5
M12
M13
M14
M15
M16A
M16B
M16

BCS Absolute Radiance Difference, (SRV0545-6)



BCS Absolute Radiance Difference, (SRV0545-6)