Polarization Factors Repeats at −45, 11 HAM A
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
0
5
10
15
20
25
30

Polarization Factors Repeats at −30, 11 HAM A
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8

Polarization Factors Repeats at −8, 11 HAM A
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8


Polarization Factors Repeats at 45, I1 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0
5
10
15
20
25
30
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, 12 HAM A
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4

Polarization Factors Repeats at −30, 12 HAM A
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
20
25
30

Polarization Factors Repeats at −8, 12 HAM A

Polarization Factors [%]

Detector

0.0
0.5
1.0
1.5

0
5
10
15
20
25
30


Polarization Factors Repeats at 45, I2 HAM A
Polarization Factors [%]
0.0
0.5
1.0
1.5
0
5
10
15
20
25
30
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −30, M1 HAM A
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15

Polarization Factors Repeats at −8, M1 HAM A

Polarization Factors [%]

0.0
0.5
1.0
1.5

0
5
10
15

Detector

Polarization Factors Repeats at 22, M1 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.5
1.0
1.5
2.0


Polarization Factors Repeats at 45, M1 HAM A
Polarization Factors [%]
2.5
2.0
1.5
1.0
0.5
0.0
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −30, M2 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0

Polarization Factors Repeats at −8, M2 HAM A
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0

Polarization Factors Repeats at 22, M2 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2


Polarization Factors Repeats at 45, M2 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
Detector
+ FP11 BVONIR w/ Sonoma (1)
* (2)
◇ (3)
△ (4)
□ (5)

Polarization Factors Repeats at −30, M3 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8

Polarization Factors Repeats at −8, M3 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8

Polarization Factors Repeats at 22, M3 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8


Polarization Factors Repeats at 45, M3 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M4 HAM A
Detector
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
Polarization Factors [%]

Polarization Factors Repeats at −30, M4 HAM A
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
1.0
1.2
0
5
10
15

Polarization Factors Repeats at −8, M4 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4


Polarization Factors Repeats at 45, M4 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M5 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4

Polarization Factors Repeats at −30, M5 HAM A
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at −8, M5 HAM A

Polarization Factors [%]

Detector

0.0
0.2
0.4
0.6
0.8
1.0
1.2

0
5
10
15


Polarization Factors Repeats at 45, M5 HAM A
Polarization Factors [%]
1.0
0.8
0.6
0.4
0.2
0.0
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M6 HAM A
Polarization Factors [%]
0.0
0.1
0.2
0.3
0.4
0.5
0
5
10
15
Detector

Polarization Factors Repeats at −30, M6 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.1
0.2
0.3
0.4

Polarization Factors Repeats at −8, M6 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.1
0.2
0.3
0.4


Polarization Factors Repeats at 45, M6 HAM A
Polarization Factors [%]
0.0
0.1
0.2
0.3
0
5
10
15
Detector
+ FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M7 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at −30, M7 HAM A
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at −8, M7 HAM A

Polarization Factors [%]

Detector

0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4

0
5
10
15


Polarization Factors Repeats at 45, M7 HAM A
Polarization Factors [%]
1.5
1.0
0.5
0.0
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, 11 HAM B
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8

Polarization Factors Repeats at −30, 11 HAM B
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8

Polarization Factors Repeats at −8, 11 HAM B
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8
1.0


Polarization Factors Repeats at 45, I1 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
0
5
10
15
20
25
30
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, 12 HAM B
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4

Polarization Factors Repeats at −30, 12 HAM B
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
20
25
30

Polarization Factors Repeats at −8, 12 HAM B
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.5
1.0
1.5


Polarization Factors Repeats at 45, I2 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
0
5
10
15
20
25
30
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −30, M1 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.5
1.0
1.5

Polarization Factors Repeats at −8, M1 HAM B

Polarization Factors [%]

0.0
0.5
1.0
1.5

0
5
10
15

Detector

Polarization Factors Repeats at 22, M1 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.5
1.0
1.5
2.0


Polarization Factors Repeats at 45, M1 HAM B
Polarization Factors [%]
2.5
2.0
1.5
1.0
0.5
0.0
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −30, M2 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at −8, M2 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at 22, M2 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4


Polarization Factors Repeats at 45, M2 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −30, M3 HAM B
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
0
5
10
15

Polarization Factors Repeats at −8, M3 HAM B
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8

Polarization Factors Repeats at 22, M3 HAM B
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
1.0
0
5
10
15


Polarization Factors Repeats at 45, M3 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M4 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0

Polarization Factors Repeats at −30, M4 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at −8, M4 HAM B
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4


Polarization Factors Repeats at 45, M4 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M5 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4

Polarization Factors Repeats at −30, M5 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4

Polarization Factors Repeats at −8, M5 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2


Polarization Factors Repeats at 45, M5 HAM B
Polarization Factors [%]
1.0
0.8
0.6
0.4
0.2
0.0
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M6 HAM B
Polarization Factors [%]
Detector
0.0
0.1
0.2
0.3
0.4
0.5
0
5
10
15

Polarization Factors Repeats at −30, M6 HAM B
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.1
0.2
0.3
0.4

Polarization Factors Repeats at −8, M6 HAM B

Polarization Factors [%]

0.0
0.1
0.2
0.3
0.4

0
5
10
15

Detector


Polarization Factors Repeats at 45, M6 HAM B
Polarization Factors [%]
0.0
0.1
0.2
0.3
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma (1)
(2)
(3)
(4)
(5)

Polarization Factors Repeats at −45, M7 HAM B
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at −30, M7 HAM B
Detector
0
5
10
15
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2

Polarization Factors Repeats at −8, M7 HAM B
Detector
Polarization Factors [%]
0
5
10
15
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4


Polarization Factors Repeats at 45, M7 HAM B
Polarization Factors [%]
1.5
1.0
0.5
0.0
0
5
10
15
Detector
+ FP11 BVONIR w/o Sonoma (1)
* (2)
◇ (3)
△ (4)
□ (5)

Polarization Factors at −8, 11 HAM A
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.2
0.4
0.6
0.8
+ FP11 BV0NIR w/o Sonoma
* FP11 BV0777 w/o Sonoma

Polarization Factors at −8, 12 HAM A
Detector
0
5
10
15
20
25
30
Polarization Factors [%]
0.0
0.5
1.0
1.5
+ FP11 BV0NIR w/o Sonoma
* FP11 BV0777 w/o Sonoma


Polarization Factors at −8, M1 HAM A
Polarization Factors [%]
0.0
0.5
1.0
1.5
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma
FP11 BV0777 w/ Sonoma


Polarization Factors at −8, M2 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma
FP11 BV0777 w/ Sonoma


Polarization Factors at −8, M3 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
0
5
10
15
Detector
FP11 BV0NIR w/ Sonoma
FP11 BV0777 w/ Sonoma


Polarization Factors at −8, M4 HAM A
Polarization Factors [%]
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0.0
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma


Polarization Factors at −8, M5 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma


Polarization Factors at −8, M6 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma


Polarization Factors at −8, M7 HAM A
Polarization Factors [%]
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0.0
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma

Polarization Factors at −8, 11 HAM B
Polarization Factors [%]
Detector
0.0
0.2
0.4
0.6
0.8
1.0
0
5
10
15
20
25
30
+ FP11 BV0NIR w/o Sonoma
* FP11 BV0777 w/o Sonoma

Polarization Factors at −8, 12 HAM B
Detector
Polarization Factors [%]
0
5
10
15
20
25
30
0.0
0.5
1.0
1.5
+ FP11 BV0NIR w/o Sonoma
* FP11 BV0777 w/o Sonoma


Polarization Factors at −8, M1 HAM B
Polarization Factors [%]
2.0
1.5
1.0
0.5
0.0
0
5
10
15
Detector
+ FP11 BVONIR w/ Sonoma
FP11 BV0777 w/ Sonoma


Polarization Factors at −8, M2 HAM B
Polarization Factors [%]
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0.0
0
5
10
15
Detector
FP11 BVONIR w/ Sonoma
FP11 BV0777 w/ Sonoma


Polarization Factors at −8, M3 HAM B
Polarization Factors [%]
1.0
0.8
0.6
0.4
0.2
0.0
0
5
10
15
Detector
+ FP11 BVONIR w/ Sonoma
* FP11 BV0777 w/ Sonoma


Polarization Factors at −8, M4 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma


Polarization Factors at −8, M5 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma


Polarization Factors at −8, M6 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma


Polarization Factors at −8, M7 HAM B
Polarization Factors [%]
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0.0
0
5
10
15
Detector
FP11 BVONIR w/o Sonoma
FP11 BVO777 w/o Sonoma


Polarization Factors, I1 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
−60
−40
−20
0
20
40
60
Scan Angle
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


Polarization Factors, I1 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
25
30
35
40
45
50
55
60
HAM AOI
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


Polarization Factors, I2 HAM A
Polarization Factors [%]
0.0
0.5
1.0
1.5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Factors, I2 HAM A
Polarization Factors [%]
0.0
0.5
1.0
1.5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Factors, M1 HAM A
Polarization Factors [%]
2.5
2.0
1.5
1.0
0.5
0.0
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M1 HAM A
Polarization Factors [%]
0.0
0.5
1.0
1.5
2.0
2.5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M2 HAM A
Polarization Factors [%]
1.5
1.0
0.5
0.0
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M2 HAM A
Polarization Factors [%]
1.5
1.0
0.5
0.0
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M3 HAM A
Polarization Factors [%]
1.0
0.8
0.6
0.4
0.2
0.0
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M3 HAM A
Polarization Factors [%]
1.0
0.8
0.6
0.4
0.2
0.0
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M4 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M4 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M5 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M5 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M6 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M6 HAM A
Polarization Factors [%]
0.0
0.2
0.4
0.6
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M7 HAM A
Polarization Factors [%]
1.5
1.0
0.5
0.0
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M7 HAM A
Polarization Factors [%]
0.0
0.5
1.0
1.5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, I1 HAM B
Polarization Factors [%]
1.0
0.8
0.6
0.4
0.2
0.0
−60
−40
−20
0
20
40
60
Scan Angle
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


Polarization Factors, I1 HAM B
Polarization Factors [%]
1.0
0.8
0.6
0.4
0.2
0.0
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Factors, I2 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Factors, I2 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Factors, M1 HAM B
Polarization Factors [%]
2.5
2.0
1.5
1.0
0.5
0.0
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M1 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
2.0
2.5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M2 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M2 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M3 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M3 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M4 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M4 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M5 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M5 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M6 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M6 HAM B
Polarization Factors [%]
0.0
0.2
0.4
0.6
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M7 HAM B
Polarization Factors [%]
1.5
1.0
0.5
0.0
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Factors, M7 HAM B
Polarization Factors [%]
0.0
0.5
1.0
1.5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, I1 HAM A
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Phase, I1 HAM A
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Phase, I2 HAM A
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


Polarization Phase, I2 HAM A
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Phase, M1 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M1 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M2 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M2 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M3 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M3 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M4 HAM A
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M4 HAM A
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M5 HAM A
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M5 HAM A
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M6 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M6 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M7 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
6
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M7 HAM A
Polarization Phase [radians]
0
1
2
3
4
5
6
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, I1 HAM B
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Phase, I1 HAM B
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Phase, I2 HAM B
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


Polarization Phase, I2 HAM B
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Polarization Phase, M1 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M1 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M2 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M2 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M3 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M3 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M4 HAM B
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M4 HAM B
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M5 HAM B
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M5 HAM B
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M6 HAM B
Polarization Phase [radians]
0
1
2
3
4
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M6 HAM B
Polarization Phase [radians]
0
1
2
3
4
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M7 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
6
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


Polarization Phase, M7 HAM B
Polarization Phase [radians]
0
1
2
3
4
5
6
25
30
35
40
45
50
55
60
HAM AOI
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, I1 HAM A
0.000
−0.002
−0.004
−0.006
−0.008
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


D_2, I1 HAM A
0.010
0.005
0.000
−0.005
−0.010
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


C_2, I2 HAM A
0.010
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


D_2, I2 HAM A
0.005
0.000
−0.005
−0.010
−0.015
−0.020
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


C_2, M1 HAM A
0.01
0.00
−0.01
−0.02
−0.03
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M1 HAM A
0.010
0.005
0.000
−0.005
−0.010
−0.015
−0.020
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M2 HAM A
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M2 HAM A
0.010
0.005
0.000
−0.005
−0.010
−0.015
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M3 HAM A
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M3 HAM A
0.010
0.005
0.000
−0.005
−0.010
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M4 HAM A
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M4 HAM A
0.000
−0.002
−0.004
−0.006
−0.008
−0.010
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M5 HAM A
0.005
0.000
−0.005
−0.010
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M5 HAM A
0.02
0.01
0.00
−0.01
−0.02
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M6 HAM A
C_2
0.004
0.002
0.000
−0.002
−0.004
−0.006
−0.008
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M6 HAM A
0.008
0.006
0.004
0.002
0.000
−0.002
−0.004
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M7 HAM A
C_2
0.005
0.000
−0.005
−0.010
−0.015
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M7 HAM A
0.005
0.000
−0.005
−0.010
−0.015
−0.020
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, I1 HAM B
0.000
−0.002
−0.004
−0.006
−0.008
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


D_2, I1 HAM B
0.010
0.005
0.000
−0.005
−0.010
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


C_2, I2 HAM B
0.010
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32


D_2, I2 HAM B
0.005
0.000
−0.005
−0.010
−0.015
−0.020
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


C_2, M1 HAM B
0.01
0.00
−0.01
−0.02
−0.03
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M1 HAM B
0.01
0.00
−0.01
−0.02
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M2 HAM B
0.010
0.005
0.000
−0.005
−0.010
−0.015
−0.020
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M2 HAM B
0.010
0.005
0.000
−0.005
−0.010
−0.015
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M3 HAM B
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M3 HAM B
0.010
0.005
0.000
−0.005
−0.010
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M4 HAM B
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M4 HAM B
0.000
−0.002
−0.004
−0.006
−0.008
−0.010
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M5 HAM B
0.005
0.000
−0.005
−0.010
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M5 HAM B
0.02
0.01
0.00
−0.01
−0.02
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M6 HAM B
0.004
0.002
0.000
−0.002
−0.004
−0.006
−0.008
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M6 HAM B
0.008
0.006
0.004
0.002
0.000
−0.002
−0.004
−0.006
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


C_2, M7 HAM B
0.005
0.000
−0.005
−0.010
−0.015
C_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16


D_2, M7 HAM B
0.005
0.000
−0.005
−0.010
−0.015
−0.020
D_2
−60
−40
−20
0
20
40
60
Scan Angle
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16