Detector Variation in a0 (warm-up)



Detector Variation in Gain (1/a1) (warm-up)



Detector Variation in a2 (warm-up)




Detector Variation in a0 (warm-up)
I4 (quadratic poly_fit)
I5 (quadratic poly_fit)
M12 (quadratic poly_fit)
M13 (quadratic poly_fit)
a0
Detector
0.0008
0.0006
0.0004
0.0002
0.0000
0.04
0.02
0.00
−0.02
−0.04
−0.06
0.0003
0.0001
−0.0001
−0.0002
−0.0006
0
5
10
15
20
30
40
HAM A, SS1
HAM B, SS1
HAM A, SS2
HAM B, SS2


Detector Variation in a0 (warm-up)
M14 (quadratic poly_fit)
M15 (quadratic poly_fit)
M16A (quadratic poly_fit)
M16B (quadratic poly_fit)
a0
Detector
0.055
0.050
0.045
0.040
0.035
0.030
0.025
0.022
0.020
0.018
0.016
0.014
0.012
0.010
0.008
0.050
0.045
0.040
0.035
0.030
0.025
0.020
0.015
0
5
10
15
20
HAM A, SS1
HAM B, SS1
HAM A, SS2
HAM B, SS2

Detector Variation in a0 (warm-up)



+ HAM A, SS1 ✳ HAM B, SS1 ◇ HAM A, SS2 △ HAM B, SS2


Detector Variation in Gain (1/a1) (warm-up)
I4 (quadratic poly_fit)
I5 (quadratic poly_fit)
M12 (quadratic poly_fit)
M13 (quadratic poly_fit)
Gain (1/a1)
Detector
HAM A, SS1
HAM B, SS1
HAM A, SS2
HAM B, SS2

Detector Variation in Gain (1/a1) (warm-up)




Detector Variation in a2 (warm-up)
I4 (quadratic poly_fit)
I5 (quadratic poly_fit)
M12 (quadratic poly_fit)
M13 (quadratic poly_fit)
a2
Detector
HAM A, SS1
HAM B, SS1
HAM A, SS2
HAM B, SS2


Detector Variation in a2 (warm-up)
M14 (quadratic poly_fit)
M15 (quadratic poly_fit)
M16A (quadratic poly_fit)
M16B (quadratic poly_fit)
a2
Detector
1.4×10⁻⁷
1.3×10⁻⁷
1.2×10⁻⁷
1.1×10⁻⁷
1.0×10⁻⁷
9.0×10⁻⁸
8.0×10⁻⁸
3.0×10⁻⁸
2.5×10⁻⁸
2.0×10⁻⁸
1.5×10⁻⁸
1.0×10⁻⁸
4.5×10⁻⁸
4.0×10⁻⁸
3.5×10⁻⁸
3.0×10⁻⁸
2.5×10⁻⁸
5.0×10⁻⁸
4.5×10⁻⁸
4.0×10⁻⁸
3.5×10⁻⁸
3.0×10⁻⁸
0
5
10
15
20
HAM A, SS1
HAM B, SS1
HAM A, SS2
HAM B, SS2

Detector Variation in a2 (warm-up)



+ HAM A, SS1 ✳ HAM B, SS1 ◇ HAM A, SS2 △ HAM B, SS2